



DraftSight 2017 SP3 Release Notes

List of Improvements in SP3 (August 2017):

#	Description
1036554	Improves "Rebuild All" command to behave properly when modifying fields in Drawing Properties.
1036150	Improves "Rebuild ()" method to work properly when modifying fields in Drawing Properties.
1027901	Fixes a German menu translation issue "Masseneigenschaften abrufen (Get Mass Properties)" that has been duplicated and used inappropriately for the other "Get Properties" command.
1026951	Fixes the Inconsistent results of IsolateLayer command.
1026341	Fixes EXTRACTBLOCKATTRIBUTE command so that the DXF Format Extract file (DXX) file will be generated successfully.
1025831	Enhances DraftSight 2017 to obtain successfully a license over SNL even if latency between client and server is over 100ms.
1024967	Enables "Alternate UnitSystem" with Prefix for dimensions to display < > sign.
1022869	Rectifies an unrecognized German command "XBlockAttributBearbeiten" by changing it to "XBLOCKATTRIBUTTEINGEBEN".
1022603	Rectifies the DraftSight German version incorrect Help article for the "Anpassungauswählen" command.
1017571	Improves stability when deleting dimension to avoid application not responding.
805964	Adds ability to insert angles with degrees and minutes using surveyor units.